



Photo 19 - Staff room
Temporary closure of aperture for missing airconditioning unit



Photo 20 - Histology
Large gaps between AC unit and wall allows significant ingress of rain.