



Photo 21: Roof of Nurses Hostel. Note asbestos sheeting.

Photo 22: Solar heating panels on kitchen roof. Note inadequate fixing of panels to roof sheeting.




Photo 23: Termite infested roof support posts on Female Ward.



Photo 24: Typical roof truss in Private Ward.