




Photo 29: Blocked culvert at entrance to hospital compound. Culvert is undersized. It should also be regularly maintained.




Photo 31: Close-up of dilapidated fenestration.



Photo 30: Water storage tank on Fort George hill above hospital to the West.



Photo 32: Possible site for a new car park which may also incorporate the disused tennis court at the left.