



APPENDIX D


Photographs




1. View of Victoria Hospital from across the harbour.



3. These large glass panels on the eastern face of the Paediatric Wing are very vulnerable to flying debris during a hurricane.




2. The Baron Wing with the new maternity block to the left and the water tank and part of the L-Block to the right. The Chest Wing is partly hidden in the foreground.




4. More glass and evidence of lack of maintenance on the west face of Paediatrics.

5.

General deterioration on the Paediatrics Wing. Note vertical cracks in upper and lower columns and horizontally along the bottom of the roof ring beam.




7. The administration building.



8.

The Laboratory building at the rear of the administration building. Note the slender columns and the link between the two structures.



6. A view of the multi-storey structure which houses Cardiology, Nephrology, an STD unit, nurses quarters and a cafeteria.

