



Photo JH-3: Blockwork piers to water tank collapses. Note no tying of 6" blocks to the original 8" blockwork piers.



Photo JH-4: Rotten end of support to patio roof.