


Source: D.B. Ballantyne.

Figure 3-4 Plates damaged in clarifier in Limon, Costa Rica, 1991



Source: Ray Sato.

Figure 3-5 Tank damage in Hurricane Iniki, Kauai, Hawaii