



Fig. 45 Damage along construction joints, probably due to bond distress.




Fig. 46 Diagonal tension failure of coupling beams.




Fig .47 Short column shear failure.