



FIGURE 69.—*A*, Massive destruction of some adobe houses in Antigua, Guatemala, near the center of town. *B*, Large-scale destruction of adobe houses in Guatemala City, Calle 2 and Avenida 9A (Zone 2). *C*, Collapse of adobe houses in Guatemala City, Calle 22A and 34 Avenida (Zone 5). *D*, Collapse of adobe houses in Guatemala City, Calle 22 and Avenida 32 (Zone 5).