



Photo 4. (A) The debris flow at Atalugankanda (Kegalle District). Encircled area shows that earth and rock have flowed from top of the ridge. (B) Future falls will threaten the houses at the foot of the ridge.