



*Figure 3-6 Anchorage of post. Soil depth below maximum potential depth of scour is adequate to withstand lateral and vertical loads during the base flood (after FEMA 1993a).*