



Fig. 5.7 Rocker bearing resting between sole plate above and masonry plate below, with missing keeper plate at top left (eastern end of bearing).



Fig. 5.8 Close-up of rocker bearing showing remnants of sheared keeper plate bolts at top.