



Figure 7.64 Diagonal bracing steel along east-west wall of large hanger at facilities of Aero Spacelines, Inc.

Figure 7.65 Buckling of diagonal bracing steel shown in Fig. 7.64

