

Fig. 7.13 Close up of cracking of shear wall in Fig. 7.12. Orientation is provided by the vertical black-board frame at right.




Fig. 7.14 More diagonal cracking of the same shear wall shown in Figs. 7.12 and 7.13.