

Fig. 8.3 Lecture hall of UCSB Chemistry Building where sheet metal panels fell from the ceiling.




Fig. 8.4 Close up of fallen sheet metal panel, UCSB Chemistry Building (Fig. 8.3).