



Fig. 8.10 Close up of damaged supports at back of chiller (Fig. 8.8).



Fig. 8.11 Broken mounting base of hot water pump on top of Library III Building, UCSB.