



**PHOTO 20** JOINT BETWEEN BUILDINGS H AND J  
(EASTERN FACADE)



**PHOTO 21** FLOOR CRACK AT THE JOINT,  
SEEN FROM THE WEST