



**PHOTO 43    WATER TANK ON TOP OF STAIRCASE  
OF BUILDINGS B AND D**



**PHOTO 44    DAMAGE TO BEAMS IN EASTERN CORRIDOR  
OF BUILDINGS B AND D**