



Photo 19 - External wall of the Hospital
The broken window (see plywood) may have predated Keith



Photo 20 - External wall of the Hospital
Note the retained damp and the cracks around the perimeters of wall panels.