



Photo 27 - The roof of the Utilities Block
Water collects under the waterproofing membrane.



Photo 28 - Flooding in the Hospital compound
Photograph taken from the roof of the Utilities Block 2 weeks after Keith