



Photo 5 - The roof of the Hospital covered with gravel ballast  
The gravel poses a hazard to windows in high winds  
It is intended to remove the gravel as part of the EU Rehab project



Photo 6 - Drain inlet on the roof of the Hospital  
Some leaks are traced to these locations