



Photo 9 - Cracked skylight

It is understood that one was removed by the wind during the passage of Keith




Photo 10 - Cracked skylight viewed from inside the Hospital