




Photo 21. The South elevation of the Orderlies' Dormitories.



Photo 22. The Lion's Eye Care Centre, occupying the upper three floors of the building, is not yet functional. The Accident and Emergency Ward, on the Ground Floor, is in use.



Photo 23. The harsh environment in which the Small Incinerator is located has proved to be detrimental to its condition.



Photo 24. The Delivery/Storage Annex and its entrance, as viewed from the North. The Engineer's block can be seen in the background.