



Photo 21 - Glass louvres
These provide inadequate protection against wind-driven rain and flying debris.



Photo 22 - Louvre-window hardware
Several devices were broken thus rendering the closing of louvres difficult.