



Photo 27 - General Stores

This could look even worse after an earthquake with item falling off the shelves.

<<<<<<<<  
<<<<<<<<



Photo 28 - Miscellaneous stores

Fire hazard, overloading, extreme inconvenience of access and retrieval

<<<<<<<<  
<<<<<<<<