



Photo 5 - Vulnerability to flooding

Lower floor of adjacent KMHM (background) is at the Category 2 storm-surge level

Lower floor of Laboratory is substantially lower than that of KMHM

<<<<<<<<

<<<<<<<<

<<<<<<<<



Photo 6 - Standby generator

Elevated to reduce vulnerability to flooding

This generator was not in working order at time of visit.

<<<<<<<<

<<<<<<<<

<<<<<<<<