



Photo 13 - Corridor
Leaks led to loosening and removal of floor tiles



Photo 14 - Chemistry Lab