



Photo 17 - Water-damaged ceiling



Photo 18 - Water-damaged ceiling
There was extensive damage to ceilings and floor coverings.