

**Appendix D**

**Photographs  
1 to 36**

**and**

**Lagniappe**





Photo 1: Panoramic view of the General Hospital.



Photo 3: Duncan Ward to the right. Large trees in background requiring trimming.




Photo 2: Laboratory roof in foreground (note asbestos sheeting). Administration facing camera.




Photo 4: Roof of kitchen. Old elevator shaft at right, new shaft to its left.