



Photo 13: Operating theatre to the left. Note large percentage of wall with glass window panels.




Photo 14: Main hospital wards. Female above, male below. Note congestion created by parked vehicles.




Photo 15: Casualty & X-Ray at ground level; Administration above. Note unprotected glass windows.



Photo 16: Duncan Ward above. Existing hoods over windows could be modified to act as storm shutters during a hurricane.