



Photo 17: Private Ward undergoing repairs. Note excellent shape characteristics both for earthquake and hurricane resistance. Hoods can be adapted to act as hurricane shutters.



Photo 18: Front view of Private Ward.



Photo 19: Doctors Quarters with unused toilets to the right. Both buildings have been recommended for demolition.



Photo 20: Roof of Psychiatric Ward. Roof vents would be more effective if located at ridge.