




Photo 25: Typical roof truss in Femal Ward.

Photo 27:
Electrical
transformer on
pole to north-west
of hospital
compound.
Transmission line
to the top of pole,
distribution lines
at mid-height.




Photo 26: Narrow access road to hospital could create traffic bottleneck during an emergency.



Photo 28: Electrical distribution wires suspended on poles on hospital compound. These are prone to damage during a hurricane and should be buried.