

Photo M-5: Rotting, 1st-floor boarding in two-storey ward.




Photo M-6: Isolation ward - shutters falling off.




Photo M-7. Male Dormitory Ward.