



Figure 3-3: 42-story high-rise concrete buildings in Cairo experienced only nonstructural damage.



Figure 3-4: Nonstructural horizontal cracks in a 14-story concrete-frame building.