



photo NO. 6 crack in the ground




photo NO. 7 utility is broken




photo NO. 8 column is broken




photo NO. 9 tile is omitted




photo NO 10 tile is cracked