

Bagmara Village, Bhiman V.D.C.



Several houses and agricultural lands were destroyed by a debris flow at Bagmara Village.



Kamala River





River bank erosion is continuing and taking rice fields trees, even after the major flood in July 1993.