



▲The Kobe municipal office building whose sixth floor was collapsed. There were some other buildings whose certain floors were destroyed.

Damage to buildings



▲ A damaged building. The first floor was crushed. Damage like this was observed in most buildings with fewer walls on the first floor, such as parking places and shops.



◀ A damaged building.