


Damage to wooden houses



◀ Destroyed houses and citizens engaged in rescue activity in Higashinada Ward, Kobe.



◀ A row of wooden houses destroyed in Higashinada Ward, Kobe. Many people were crushed to death under houses and furniture.



◀ A destroyed wooden house in Hokudan-cho, Awaji Island.