

APPENDIX B

Photographs

Castries




Photo 1: Administrative Office Building



Photo 3: Atrium roof, Administrative Offices




Photo 2: Drainage canal adjacent to site of Administrative Offices



Photo 4: Rafter/beam connection, Administrative Offices atrium roof

Photo 7: Skylight to
staircase,
Administrative Offices





Photo 5: Door to the roof, Administrative Offices




Photo 6: Roof, Administrative Offices




Photo 8: Atrium windows, Administrative Offices




Photo 9: Various installations, Administrative Offices roof




Photo 10: Drainage outlet, Administrative Offices roof




Photo 11: Sub-station



Photo 12: View of inside, Sub-station