



Photo 62: J-bolt fixing to asbestos sheeting



Photo 63: View of J-bolt fixing to show end which may straighten out




Photo 64: Door opening to Power Station



Photo 65: Power Station
Exhaust Stacks




Photo 68: Top stay, Exhaust Stack




Photo 69: Fuel Tank
not attached to supporting
frame, Power Station




Photo 66: Base detail, Exhaust Stacks support




Photo 67: Exhaust Stack resting on support; pipe connection to engine
(upper left corner)



Photo 70: Water Tank to left of Power Station




Photo 72: Fuel Tanks supports, Power Station



Photo 71: Fuel Tanks, Power Station