

APPENDIX D

Photographs



Photo 1: Castries sub-station: Currently under construction, most of the equipment to be used here was stored at Union and was damaged during the floods. Construction is now behind schedule.




Photo 2: Castries sub-station compound - no significant flooding was reported to have occurred inside the compound. However the adjacent road was said to have been under about 12" of water.



Photo 3: Union sub-station: water levels during the flood were reported to have been at least 5' to 6' above floor level. The approximate water level outside the building is indicated on the photograph.



Photo 4: Union power station, on higher ground than the substation, was not affected by the flood. However, the generating facilities had to be shut down after the sub-station was flooded.



Photo 5: This cliff face, behind the sub-station at Union, forms the southern side of the Choc River valley.




Photo 6: The storehouse at Union is not normally used to store any significant items, however, the Castries sub-station equipment was stored here at the time of the flood.



Photo 7: Drainage ditch outside the power station. The Choc River is located on the left hand side of the road. The river bed is about 10' to 12' below road level.



Photo 8: The small sub-station under construction near Soufriere.




Photo 9: Retaining wall at the rear of the Soufriere sub-station.