



FIGURE 1.10 Upstream view of Salado River, showing location of bedrock constriction (white arrows) that caused short-lived damming of the river. Note trimline in jungle cover along lower valley wall upstream of the river constriction. This trimline indicates position of the shoreline that was formed by damming of the river to a level 10-15 m above current river level.

REFERENCES

- Costa, J. E., and R. L. Schuster. 1988. The formation and failure of natural dams. *Geological Society of America Bulletin*, 100:1054-1068.
- Costa, J. E., and R. L. Schuster. 1991. Documented Historical Landslide Dams from Around the World. U.S. Geological Survey Open-File Report 91-239:486.
- Crespo, E., K. J. Nyman, and T. D. O'Rourke. 1987. Ecuador Earthquakes of March 5, 1987. Earthquake Engineering Research Institute Special Earthquake Report, 4.
- Garwood, N. C., D. P. Janos, and N. Brokaw. 1979. Earthquake-caused landslides: A major disturbance to tropical forests. *Science* 205(4410, 7 September):997-999.
- Hakuno, M., S. Okusa, and M. Michiue. 1988. Study Report of Damage Done by the 1987 Earthquakes in Ecuador. Research Report on Unexpected Disasters, Research Field Group, Natural Disasters and the Ability of the Community to Resist Them, Supported by the Japanese Ministry of Education, Culture, and Science (Grant No. 626010221), 38.
- Keefer, D. K. 1984. Landslides caused by earthquakes. *Geological Society of America Bulletin* 95:406-421.

- Marshall, A. J. 1937. Northern New Guinea, 1936. *Geographical Journal* 89(6):489–506.
- Nieto, A. S., and R. L. Schuster. 1988. Mass wasting and flooding induced by the 5 March 1987 Ecuador earthquakes. *Landslide News*, newsletter of The Japan Landslide Society, 2:1–3.
- Okusa, S., M. Hakuno, and M. Michiue. 1989. Distribution of factors of safety for natural slope stability—an example of Ecuador. *Proceedings of the Japan-China Symposium on Landslides and Debris Flows*. Niigata, October 3, Tokyo, October 5, The Japan Landslide Society and The Japan Society of Erosion Control Engineering:273–278.
- Pain, C. F. 1972. Characteristics and geomorphic effects of earthquake-initiated landslides in the Adelbert Range, Papua New Guinea. *Engineering Geology* 6(4):261–274.
- Pain, C. F., and J. M. Bowler. 1973. Denudation following the November 1970 earthquake at Madang, Papua New Guinea. *Zeitschrift für Geomorphologie Suppl. Bd.* 18:92–104.
- Schuster, R. L., and J. E. Costa. 1986. A perspective on landslide dams. Pp. 1–20 in *Landslide Dams: Processes, Risk, and Mitigation*, R. L. Schuster, ed. Geotechnical Special Publication No. 3, American Society of Civil Engineers.
- Simonett, D. S. 1967. Landslide distribution and earthquakes in the Bewani and Torricelli Mountains, New Guinea. Pp. 64–84 in *Landform Studies from Australia and New Guinea*, J. N. Jennings and J. A. Mabbutt, eds. Canberra: Australian National University Press.
- Stanley, G. A. V. 1935. Preliminary notes on the recent earthquake in New Guinea. *Australian Geographer* 2(8):8–15.
- Veblen, T. T., and D. H. Ashton. 1978. Catastrophic influences on the vegetation of the Valdivian Andes, Chile. *Vegetation* 36(3):149–167.
- Xue-Cai, F., and G. An-ning. 1986. The principal characteristics of earthquake landslides in China. *Geología Aplicada e Idrogeología* 21(2):27–45.