



FIGURE 6.6 Pipeline broken by a debris flow that has eroded 6 m below the pipeline right of way.



FIGURE 6.7 Flooding along the Coca River. Note the broken and deformed pipeline at the left side of the photograph.