

Figure 3 Damage to the Railway System,
courtesy: Kobe University





Figure 4 Damage to the Highway Networks,
courtesy: Kobe University






Photo 10 Railway Damage Hanshin Honsen Line
Elevated railyards and stations suffered structural damage
Hyogo Prefectural Government



Photo 11 Artery Road Cut by Ground Failure
Ground liquefaction made roads impassable
Hyogo Prefectural Government