



Figure 2. Flat bottomed, steep sided sand boil which does not have a cone of deposited sand associated with it, located near the mouth of the Villalobos River at La Playa, Guatemala.




Figure 3. Diagram of a lateral spreading landslide (after Varnes, 1978).




Figure 4. Airphoto of the El Sauzal and La Playa portions of the delta at Lake Amatitlan. The subsided 1922 lobe of the delta is marked by a few bushes poking up out of the lake waters. Many white patches are ejected sand caused by liquefaction. Dates of river outlets were given by local residents. (U-2 photography taken 13 February, 1976, by the U.S. Air Force under contract to the Office of Foreign Disaster Assistance of A.I.D., U.S. Department of State.)