


photo: EQE, Inc.



Jose Maria Morelos Dam. The dam and La Villita power station are located near the mouth of the Rio Balsas. earth-filled dam is approximately I5 feet high by 1,000 feet long. The large array of high voltage equipmen in the station switchyard (adjacent the dam crest) was unaffected by the earthquake, even though this type of equipment is often susceptable to seismic damage. The power station i housed in a large steel frame build: and consists of four 76 megawatt units, completed in 1973. Mechnica and electrical equipment in the station were undamaged by the earthquake. Protective relays disconnected the station from the power grid during the earthquake.